	,		BEST AVAIL	ABLE C	OPY	···	r=1	
	Туре	Hits	Search Text	DBs	Time Stamp	m	f	Err
1	BRS	12	ferroelectric with oxygen with deficiency	USPAT; EPO; JPO; DERWENT; IBM	2001/07 /18 16:06			0
2	BRS	627	ferroelectric with oxygen	USPAT; EPO; JPO; DERWENT; IBM	/18			0
3	BRS	12	(ferroelectric with oxygen) and 257\$3.ccls.	USPAT; EPO; JPO; DERWENT; IBM	/18			0
4	BRS	115	(ferroelectric with oxygen) and 257/\$3.ccls.	USPAT; EPO; JPO; DERWENT; IBM	/19			0
5	BRS	3	(ferroelectric with oxygen with implant\$7)	USPAT; EPO; JPO; DERWENT; IBM	/19	•	****	0
6	BR\$	84	(ferroelectric and (oxygen with implant\$7))	USPAT; EPO; JPO; DERWENT; IBM	2001/07 /19 13:00			0